DART AEROSPACE LTD			Work Order:	41373	
n _e					
Description: Tetlan Bushing	-A ₄		Part Number:	PR67-43001-26	
Inspection Dwg: Rev: X				Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST


X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
01 595	+.000 +.005 +.015	01594	V			
03 1.275	+ 010	1.275	V			
2.00	± 030	1,99	\checkmark			
	1					
	-					
						`
		_				
					·	7
		,				
						i.
				1		
		d.				

Measured by:	Audited by:	and	Prototype Approval:	NA
Date: 08(09/8	Date:	08/09/19	Date:	

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	





Date:

Friday, 12/09/2008 9:52:24 AM

User:

, V Jean-Luc Menard

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: TEFLON BUSHING

Job Number: 41373

Part Number: PB6743001265

Job Number:

Seq. #:

Machine Or Operation:

Description:

6.0

FINAL INSPECTIONW/O RELEASE

08/09/19 de 19/19

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion





Date: User: Friday, 12/09/2008 9:52:24 AM

Jean-Luc Menard

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Type

: Est. A 05.07.19

Job Number

: 41373

Estimate Number

: 12070

P.O. Number This Issue

: 12/09/2008

S.O. No. :

: NC Prsht Rev.

First Issue

: 18/08/2008

: 40056 **Previous Run**

Written By

Checked & Approved By

Comment

: MACHINED PARTS

New issue KJ/JLM

Drawing Name

: TEFLON BUSHING

Part Number Drawing Number : PB6743001265 : B6743001 PAGE20

Project Number

: N/A : B1

Drawing Revision Material

: 18/09/2008 **Due Date**

Qty:

60 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

MDELRINR1750

DELRIN ROUND BAR 1.750



Comment: Qty.:

0.1838 f(s)/Unit Total:

11.0250 f(s)

DELRIN ROUND BAR 1.750 Material: Delrin Bar Ø1.750 (M-DELRIN-R1.750) Identify for B67-43001-265

Batch: <u>M109020</u>

2.0

Comment: HARDINGE CNC LATHE SMALL

Turn as per Dwg B67-43001

Deburr

HARDINGE

Dwg Rev: 🔽

3.0 QC2 PECT PARTS AS THEY COME OFF MACHINE





muz 08/09/18



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



Comment: SECOND CHECK



5.0 PACKAGING 1 PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

